



Lawrence Berkeley Laboratory

UNIVERSITY OF CALIFORNIA

RECEIVED
LAWRENCE
BERKELEY LABORATORY

Materials & Molecular Research Division

FEB 21 1984

LIBRARY AND
DOCUMENTS SECTION

Presented at the Symposium on Electron Microscopy of
Materials, Boston, MA, November 14-17, 1983


HIGH RESOLUTION TEM STUDIES OF DEFECTS NEAR Si-SiO₂
INTERFACE

J.H. Mazur and J. Washburn

November 1983

TWO-WEEK LOAN COPY

*This is a Library Circulating Copy
which may be borrowed for two weeks.
For a personal retention copy, call
Tech. Info. Division, Ext. 6782.*



LBL-17114
c.2

DISCLAIMER

This document was prepared as an account of work sponsored by the United States Government. While this document is believed to contain correct information, neither the United States Government nor any agency thereof, nor the Regents of the University of California, nor any of their employees, makes any warranty, express or implied, or assumes any legal responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by its trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof, or the Regents of the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof or the Regents of the University of California.

HIGH RESOLUTION TEM STUDIES OF DEFECTS NEAR Si-SiO₂ INTERFACE

J. H. Mazur and J. Washburn
Materials and Molecular Research Division
Lawrence Berkeley Laboratory
University of California
Berkeley, California 94720

ABSTRACT

Small defects with habit parallel to {100} and {311} matrix planes were observed using high resolution transmission electron microscopy (HREM) within 100 nm from the Si-SiO₂ interfaces after one step oxidation in dry O₂ at 900°C, 1000°C and 1150°C of Czochralski (CZ) grown [100] p-type boron doped, 1.5 - 20 Ω cm Si wafers with concentrations of oxygen $1.4 \times 10^{18} \text{cm}^{-3}$ and carbon $4. - 10. \times 10^{16} \text{cm}^{-3}$. The defects were less than 10 nm wide and 1 nm thick. The {100} and {311} defect are interpreted tentatively as thin silica platelets and {311} stacking faults respectively. Distribution of defects near the interface was random although their density appeared to be lower for higher oxidation temperatures. It is not yet clear whether the defects were formed during the oxidation treatments or were present near the surfaces of the as-received wafers.

INTRODUCTION

Silicon crystals grown from quartz crucibles by the Czochralski method typically contain 10^{18}cm^{-3} interstitially dissolved oxygen. This corresponds approximately to the oxygen solid solubility limit at the melting temperature. Thus during processing steps in production of electronic devices involving lower temperature heat treatments, oxygen precipitation from supersaturated solid solution can result [1]. The defects formed are beneficial for gettering metallic impurities if they are away from the active device regions [2,3,4]. However the presence of precipitates within active regions of the devices can be detrimental to performance. For example, higher generation current has been observed in MOS capacitors if these defects are found within the depletion region [5] or near p-n junctions [6]. In this paper, preliminary observations of defects within the depth of the depletion width from the Si-SiO₂ interface are reported in wafers after a one-step oxidation at temperatures above 900°C.

The defects were observed during a systematic investigation of the Si-SiO₂ interface structure using lattice imaging electron microscopy of cross-sectional specimens.

EXPERIMENTAL PROCEDURES

Commercially supplied (without specification of thermal history) Czochralski-grown Si [100] wafers, p-type boron doped $1.5 - 20 \text{ cm}^{-3}$ were used for oxidation. These wafers contained $1.4 \times 10^{18} \text{cm}^{-3}$ oxygen and 4 to $10 \times 10^{16} \text{cm}^{-3}$ of carbon atoms as estimated from I.R. measurements.

The wafers were cleaned in a series of rinses including:
(1) 5:1:1 H₂O: NH₄OH:H₂O₂, (2) deionized water (D.I.), (3) 5:1:1 H₂O:HCl:H₂O₂, (4) D.I., (5) 50:1 H₂O:HF, (6) D.I., and after drying in N₂ were transferred into the furnace with an argon atmosphere. After five minutes the argon was replaced by dry oxygen for the desired time. The wafers were removed from the hot zone of the furnace after again changing to argon ambient during a two minute interval. The oxidations were performed at 900°C, 1000°C, and 1150°C, for times necessary to grow oxide layers 20 nm to 100 nm thick.

Cross-sectional TEM specimens were prepared using the standard technique [7]. High resolution TEM images were obtained using a JEM 200 CX electron microscope operating at 200 kV and equipped with high resolution pole piece. The electron beam parallel to the zone axis [011] allowed resolution of two sets of {111} planes in the silicon crystal edge on. The distance between {111} fringes corresponds to the distance 0.314 nm spacing of silicon {111} lattice planes.

EXPERIMENTAL RESULTS AND DISCUSSION

Observations in the vicinity of the Si-SiO₂ interface within a distance of about one micron were performed on the first set of specimens with about 200 nm of oxide grown at 900°C for 120 minutes. Two characteristic classes of defects were observed and are shown in Fig. 1. The defects marked "a" in Fig. 1 are tentatively interpreted as silica precipitate platelets growing on 100 matrix planes. Larger defects having similar contrast have been observed in plan view silicon specimens prepared from CZ silicon crystals after anneals at 870°C and 650°C and are commonly known as "black dot" defects [8,9]. Figs. 2 and 3 show higher magnifications of platelet defects marked in Fig. 1 by "a₁", and "a₂" respectively. The observed dimensions varied from 4 nm to 10 nm. The thickness was estimated to be 0.3 - 0.6 nm. A second type of defects which appeared occasionally near the platelets are indicated by "b" in Figs. 1, 3. These defects are parallel to {311} matrix planes. They also have been previously observed in CZ silicon and have been called {311} stacking faults [10]. Other authors [8,9] have considered them to be

precipitates growing on the {311} matrix planes. They may be elongated in the $\langle 110 \rangle$ direction parallel to the beam and thus observed as a cross section 3-4 nm in width [11]. The density of the {311} defects appeared to be lower than that of the platelets and the distribution of both types of defects appeared to be random within about 100 nm from the Si-SiO₂ interface.

For the wafers oxidized at 1000°C for eight minutes similar defects were also observed. Figure 4 shows two {100} precipitates within 15 nm of the Si-SiO₂ interface. The dimensions and contrast are similar to the "a" defects observed at 900°. The {311} defects were also observed at a somewhat greater distance from the Si-SiO₂ interface. The density of both defects was lower than in the specimen oxidized at 900°C.

Specimens oxidized at 1150°C for 25 minutes also contained similar defects as shown in Fig. 5. The density of {100} defects was considerably smaller than at 900°C and 1000°C.

To begin to establish the origin of these defects, observations were performed on cross sections of as-supplied wafers. The high resolution image of such a specimen is shown in Fig. 6. Within the area studied, a few defects were observed with similar contrast to the {311} stacking faults although smaller in size. This observation suggests that some or all of the defects may have been present in the as-received wafers. Because the density of these defects may vary markedly from one wafer to another, or from one part to another in a single wafer, it is not yet possible to conclude that these defects were formed during the oxidation treatment.

However, it is of interest that after an oxidizing anneal even at 1150°, these defects are still present very near the surface.

ACKNOWLEDGEMENTS


This work was supported by the Director, Office of Energy Research, Office of Basic Energy Sciences, Materials Sciences Division of the U.S. Department of Energy under Contract No. DE-AC03-76SF00098.

REFERENCES

1. J. R. Patel in Semiconductor Silicon 1981, H. R. Huff, R. J. Kriegler, Y. Takeishi, Eds (The Electrochemical Society, Pennington, 1981) p. 189.
2. S. M. Hu, J. Vac. Sci. Technol. 14, 17 (1977).
3. T. Y. Tan, E. E. Gardner, W. K. Tice, Appl. Phys. Lett. 30, 175 (1977).
4. W. K. Tice, T. Y. Tan, Appl. Phys. Lett. 28, 564 (1976).
5. W. J. Patrick, S. M. Hu, W. A. Westdorp, J. Appl. Phys. 50, 1399 (1979).
6. C. J. Varker, J. D. Whitfield, K. V. Rao, J. J. Demer, in Ref. 1, p. 313.
7. J. H. Mazur, R. Gronsky, J. Washburn in Inst. Phys. Conf. Ser. No. 67 (1983).
8. J. Desseaux-Thibault, A. Bourret, J. M. Pennisson, ibid.
9. F. A. Ponce, S. Hahn, T. Yamashita, M. Scot, J. Carruthers, ibid.
10. T. Y. Tan, H. Foell, S. Mader, W. Krakow, Mat. Res. Soc. Symp. Proc. 2, 179-184, (1981).
11. N. Yamamoto, P. M. Petroff, J. R. Patel, J. Appl. Phys., 54, 3475 (1983).


FIGURE CAPTIONS

- Fig. 1 HREM image of the defects near Si-SiO₂ interface after 900°C oxidation.
- Fig. 2 Higher magnification HREM image of {100} defect marked a₁ in Fig. 1.
- Fig. 3 Higher magnification HREM image of {100} and {311} defects marked a₂ and b₁, b₂ in Fig. 1.
- Fig. 4 HREM image of the {100} defects near the Si-SiO₂ interface (after 1000°C oxidation).
- Fig. 5 HREM image of the {311} defect near the interface (after 1150°C oxidation).
- Fig. 6 HREM image of the defect in as-supplied wafer.




XBB 830-10008

Fig. 1




XBB 830-10009

Fig. 2




XBB 830-10011

Fig. 3




XBB 830-10010

Fig. 4



XBB 830-10014

Fig. 5



XBB 830-10134

Fig. 6

This report was done with support from the Department of Energy. Any conclusions or opinions expressed in this report represent solely those of the author(s) and not necessarily those of The Regents of the University of California, the Lawrence Berkeley Laboratory or the Department of Energy.

Reference to a company or product name does not imply approval or recommendation of the product by the University of California or the U.S. Department of Energy to the exclusion of others that may be suitable.

TECHNICAL INFORMATION DEPARTMENT
LAWRENCE BERKELEY LABORATORY
UNIVERSITY OF CALIFORNIA
BERKELEY, CALIFORNIA 94720